ASBESTOS ASSE

H-K Building 36 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH Building Number: 36

Building Name: WAREHOUSE

SEATTLE, WASHINGTON 98134

Building Type: WAREHOUSE Year Constructed: 1964

******* AREA NUMBER: 01	AREA DESCR	IPTIO	N: 1st Floor		AREA AVERAGI	X ASBE	stos:	157	4	*****	****
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE			PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
along center-north to south-at ceiling	01-356177	15%	mjp on non-suspect pipe cover	OMA	5 4 in. O.D.	LPS/R	25	111	\$140	\$78	\$218
along center-north to south-at ceiling	01-356177		mip on non-suspect pipe cover	OMA	3 6 in. O.D.	LPS/R			\$116	\$68	\$184
along east wall-at ceiling	01-356177	15%	mip on non-suspect pipe cover	OMA	2 4 in. O.D.	LPS/R	25	111	\$56	\$31	\$87
along east wall-at ceiling	01-356177	15%	mjp on non-suspect pipe cover	OHA	8 6 in. O.D.	LPS/R	25	111	\$309	\$182	\$491
	01-356178	20%						111			
	01-356179	15%						1111			
along east wall-at ceiling	02-356180	10%	mjp on non-suspect pipe cover	OMA	9 4 in. O.D.	DR	25	111	\$253	\$140	\$393
along east wall-at ceiling	02-356180	10%	mjp on non-suspect pipe cover	AHO	4 6 in. O.D.	DR	25	111	\$155	\$91	\$246
along west wall-at ceiling	02-356180	10%	mjp on non-suspect pipe cover	OMA	19 4 in. O.D.	DR		111	\$534	\$297	\$831
along west wall-at ceiling	02-356180		mjp on non-suspect pipe cover	OMA	4 6 in. 0.D.	DR	25		\$155	\$91	\$246
-	02-356181	15%						111			
	02-356182	10%	1				25	111			

AREA COMMENTS

AREA # 01 TOTAL \$1,718 \$978 \$2,696

The material is in good condition with minor contact and water damage. The material is approximately 12' to 15' from the floor. At a minimum, it is recommended that the material be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a high traffic area.

BUILDING # 36	TOTAL	\$1,718	\$978	\$2,696
BOILDING # 30	IOIAL	<b>41,710</b>	-710	45,070